

"MATERIAL TYPE/DESCRIBE"

ABBREVIATIONS

ABV ABOVE
APX APPROXIMATELY
B BOYS
BLR BOILER
BLRM BOILER ROOM
BLW BELOW
C CEILING
CLRM CLASSROOM
CRN CORNER
CT CEILING TILE
ENT ENTRANCE
DCT DROP CEILING TILE
FG FIBERGLASS
FLR FLOOR
FT FLOOR TILE
G GIRLS
H HORIZONTAL
HLW HALLWAY
JTS JOINTS AND FITTINGS
LG LARGE
LR LOCKER ROOM
OFC OFFICE
PS PLASTER SURFACE
RM ROOM
RR REST ROOM
SM SMALL
STG STORAGE
STR STAIRWELL
STW STAIRWAY
T TEACHERS
TNL TUNNEL
UND UNDER
V VERTICAL
WTR WATER
X- ACROSS FROM

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A.	
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	NO.
001 BOILER ROOM	T BLR EXHAUST	0 40	L	D	M	L	L	H	Y	Y	012
	M MUD JTS FG LINE	0 275	M	D	H	L	L	H	Y	N	011
002 CLASSROOM 402	M 9 X 9 FT	1150 0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0 12	L	O	L	L	L	H	N	N	011
003 JANITOR CLOSET	NO SUSP ACBM	0 0							N	N	000
004 CLRM 401 & RR & STG	M 9 X 9 FT	1150 0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0 4	L	O	L	L	L	H	N	N	011
005 CLRM 404 & RR & STG	M 9 X 9 FT	1150 0	L	O	L	L	L	L	Y	Y	010
	T FG JOINTS	0 19	L	O	L	L	L	H	N	N	011
006 CLRM 403A & RR	M 9 X 9 FT	1150 0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0 6	L	O	L	L	L	H	N	N	011
007 CLASSROOM 301	M 9 X 9 FT	800 0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0 12	L	O	L	L	L	H	N	N	011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES				
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
008 RR AND STORAGE	M 9 X 9 FT	100	0	L	O	L	L	L	L	N	Y	010
009 CLASSROOM 302	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	10	L	O	L	L	L	H	N	N	011
010 CLASSROOM 303	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	14	L	O	L	L	L	H	N	N	011
011 RR COMMON AREA BY 303-306M	9 X 9 FT	175	0	L	O	L	L	L	L	N	Y	010
012 CLASSROOM 306	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	12	L	O	L	L	L	H	N	N	011
013 PLANNING RM BY RM 303	M 9 X 9 FT	100	0	L	O	L	L	L	L	N	Y	010
014 JANITOR CLOSET	NO SUSP ACBM	0	0							N	N	000
015 CLASSROOM 304	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	12	L	O	L	L	L	H	N	N	011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR			FRI-	ASBES		
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
016												
CLASSROOM 305	M											
	9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T											
	FG JOINTS	0	12	L	O	L	L	L	H	N	N	011
017												
JANITOR CLOSET												
	NO SUSP ACBM	0	0							N	N	000
018												
PLAN RM BY ROOM 306	M											
	9 X 9 FT	100	0	L	O	L	L	L	L	N	Y	010
019												
CLASSROOM 308	M											
	9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T											
	FG JOINTS	0	12	L	O	L	L	L	H	N	N	011
020												
RR AND STG BETWN 308-307 M												
	9 X 9 FT	100	0	L	O	L	L	L	L	N	Y	010
021												
CLASSROOM 307	M											
	9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T											
	FG JOINTS	0	12	L	O	L	L	L	H	N	N	011
022												
CLRM 205 RESOURCE RM RR	M											
	9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	010
	T											
	FG JOINTS	0	9	L	O	L	L	L	H	N	N	011
023												
CLRM 206 TEACHER'S LOUNGEM												
	9 X 9 FT	775	0	L	O	L	L	L	L	N	Y	010
	T											
	FG JOINTS	0	10	L	O	L	L	L	H	N	N	011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WD AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. H.A. (Y,N,A)	NO.
024 TRANSFORMER ROOM	NO SUSP ACBM	0	0							N	N	000
025 STORAGE ROOM GYM EQUIPMNTT	FG JOINTS	0	24	L	O	L	L	L	H	N	N	011
026 2ND STORAGE ROOM	T FG JOINTS	0	14	L	O	L	L	L	H	N	N	011
027 KITCHEN RR JANITOR CLOSETT	FG JOINTS	0	2	L	O	L	L	L	H	N	N	011
028 DRY STORAGE OFF KITCHEN	T FG JOINTS	0	3	L	O	L	L	L	H	N	N	011
029 OFC & STG S SIDE MULTIPURM	9 X 9 FT T FG JOINTS	100	0	L	O	L	L	L	L	N	Y	010
030 MUSIC ROOM AND ENTRYWAY	M 9 X 9 FT	1050	0	L	O	L	L	L	L	N	Y	010
031 STG RM OFF MUSIC ROOM	NO SUSP ACBM	0	0							N	N	000
032 BLOWER RM ABV ENT MUSICRMT	FG JOINTS M	0	52	L	O	M	L	L	H	Y	N	011
033 RR AND JANITOR CLOSET	NO SUSP ACBM	0	0							N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A. NO.		
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)		CONT. (Y,N,A)	
034 OFC OFF SE CRN MUSIC RM	M 9 X 9 FT	120	0	L	O	L	L	L	L	N	Y	010
035 STG RM S SIDE OF MUSIC RM	NO SUSP ACBM	0	0							N	N	000
036 BLOW RM ABV STG ON S SIDET	FG JOINTS	0	39	L	O	M	L	L	H	N	N	011
037 GYMNASIUM MULTIPURPOSE RMM	M 9 X 9 FT	5500	0	L	O	L	L	L	L	Y	Y	010
038 ROOM 112	M 9 X 9 FT	900	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
039 ROOM 111	M 9 X 9 FT	900	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
040 ROOM 110	M 9 X 9 FT	900	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
041 ROOM 109	M 9 X 9 FT	900	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	16	L	O	L	L	L	H	N	N	011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR			FRI-	ASBES		
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
042 ROOM 108	M 9 X 9 FT T FG JOINTS	900 0	0 16	L L	O O	L L	L L	L L	L H	N N	Y N	010 011
043 ROOM 107	M 9 X 9 FT T FG JOINTS	900 0	0 16	L L	O O	L L	L L	L L	L H	Y Y	Y N	010 011
044 ROOM 106	M 9 X 9 FT T FG JOINTS	900 0	0 16	L L	O O	L L	L L	L L	L H	N N	Y N	010 011
045 ROOM 105	M 9 X 9 FT T FG JOINTS	900 0	0 16	L L	O O	L L	L L	L L	L H	N N	Y N	010 011
046 ROOM 104	M 9 X 9 FT T FG JOINTS	900 0	0 16	L L	O O	L L	L L	L L	L H	N N	Y N	010 011
047 ROOM 103	M 9 X 9 FT T FG JOINTS	900 0	0 16	L L	O O	L L	L L	L L	L H	N N	Y N	010 011
048 ROOM 102	M 9 X 9 FT T FG JOINTS	900 0	0 16	L L	O O	L L	L L	L L	L H	N N	Y N	010 011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WD KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES				
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
049 ROOM 101	M 9 X 9 FT T	900	0	L	O	L	L	L	L	N	Y	010
	FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
050 ROOM 204	M 9 X 9 FT T	900	0	L	O	L	L	L	L	N	Y	010
	FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
051 ROOM 203	M 9 X 9 FT T	900	0	L	O	L	L	L	L	N	Y	010
	FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
052 ROOM 202	M 9 X 9 FT T	900	0	L	O	L	L	L	L	N	Y	010
	FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
053 ROOM 201	M 9 X 9 FT T	900	0	L	O	L	L	L	L	N	Y	010
	FG JOINTS	0	16	L	O	L	L	L	H	N	N	011
054 STORAGE OFF ROOM 201	T FG JOINTS	0	8	L	O	L	L	L	H	N	N	011
055 RR X OFFICE & PIPE CHASE	T FG JOINTS	0	40	L	O	L	L	L	H	N	N	011
	T ROOF DRAIN FGJT	0	6	L	O	L	L	L	H	N	N	011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR		FRI-	ASBES			
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
056 MAIN OFFICE	M 9 X 9 FT	600	0	L	O	L	L	L	L	N	Y	010
057 SMALL OFFICE & PAPER STG	M 9 X 9 FT	700	0	L	O	L	L	L	L	N	Y	010
	T FG JTS	0	20	L	O	L	L	L	H	N	N	011
058 RADIO ROOM	M 9 X 9 FT	200	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	8	L	O	L	L	L	H	N	N	011
	T ROOF DRAIN FGJT	0	8	L	O	L	L	L	H	N	N	011
059 SUPPLY ROOM & HALLWAY	M 9 X 9 FT	340	0	L	O	L	L	L	L	N	Y	010
060 PRINCIPAL'S OFFICE	M 9 X 9 FT	300	0	L	O	L	L	L	L	N	Y	010
	T FG JTS	0	6	L	O	L	L	L	H	N	N	011
061 SICK ROOM	M 9 X 9 FT	130	0	L	O	L	L	L	L	N	Y	010
	T FG JTS	0	12	L	O	L	L	L	H	N	N	011
062 TV ROOM	M 9 X 9 FT	320	0	L	O	L	L	L	L	N	Y	010
063 COMPUTER ROOM	M 9 X 9 FT	700	0	L	O	L	L	L	L	N	Y	010

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF		DAMAGE POTENT.			AIR	FRI-	ASBES			
				DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
063 COMPUTER ROOM	T FG JOINTS	0	700	L	O	L	L	L	H	N	N	011
064 REST ROOMS & HALLWAY	M 9 X 9 FT	200	0	L	O	L	L	L	L	N	Y	010
	T FG JOINTS	0	4	L	O	L	L	L	H	N	N	011
065 JANITOR'S CLOSET	NO SUSP ACBM	0	0							N	N	000
	NO SUSP ACBM	0	0							N	N	000
066 MATERIALS CENTER	T FG JTS	0	12	L	O	L	L	L	H	N	N	011
067 CONFERENCE ROOM	M 9 X 9 FT	150	0	L	O	L	L	L	L	N	Y	010
068 AV ROOM	M 9 X 9 FT	400	0	L	O	L	L	L	L	N	Y	010
069 SINK ROOM	M 9 X 9 FT	150	0	L	O	L	L	L	L	N	Y	010
	T FG JTS	0	8	L	O	L	L	L	H	N	N	011
070 OFFICE	M 9 X 9 FT	100	0	L	O	L	L	L	L	N	Y	010
071 STORAGE ROOM	M 9 X 9 FT	240	0	L	O	L	L	L	L	N	Y	010

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
071 STORAGE ROOM	T FG JTS	0	4	L	O	L	L	L	H	N	N	011
072 ART ROOM	T FG JTS	0	8	L	O	L	L	L	H	N	N	011
073 ART STORAGE ROOM	T FG JTS	0	16	L	O	L	L	L	H	N	N	011
	M KILNS	50	0	L	O	M	L	L	M	Y	N	014
074 BOY'S & GIRL'S REST ROOM	T FG JTS	0	40	L	O	L	L	L	H	N	N	011
	T ROOF DRAIN	0	6	L	O	L	L	L	H	Y	N	011
	T PAPER ABV FG LN	0	3	L	O	L	L	L	H	Y	N	015
075 JANITOR'S CLOSET	NO SUSP ACBM	0	0							N	N	000
076 N SIDE W HALL	T FG JTS	0	30	L	O	L	L	L	H	N	N	011
077 MIDDLE EW HALL	T FG JTS	0	60	L	O	L	L	L	H	N	N	011
078 N SIDE E HALL	T FG JTS	0	100	L	O	L	L	L	H	Y	N	011
079 S SIDE W HALL	T FG JTS	0	50	L	O	L	L	L	H	N	N	011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD ELEMENTARY

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.		DAMAGE CAUSE		AIR	FRI-	ASBES		
		SF	LF	(L,M,H)	(DWVO)	(L,M,H)	(L,M,H)	(L,M,H)	(L,M,H)	(Y,N)	(Y,N,A)	NO.
080 S SIDE CENTER HALL	T FG JTS	0	50	L	O	L	L	L	H	N	N	011
081 S SIDE E HALL	T FG JTS	0	50	L	O	L	L	L	H	N	N	011

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A. NO.	
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)		CONT. (Y,N,A)
001 BOILER ROOM	M FIRE BRICK	3 0	H	V	H	L	L	H	Y	N	022
	M BOILER GASKET	0 8	H	V	H	L	L	H	Y	N	024
	T H WTR TANK MAG	385 0	H	D	M	L	L	H	Y	Y	026
	T HEAT LINES MAG	0 150	M	V	H	L	L	H	Y	Y	021
	T CELLULOSE WTR	0 275	H	D	H	L	L	H	Y	Y	023
	T MUD JT CELL LNS	0 140	H	D	H	L	L	H	Y	Y	023
002 TUNNELS	T POLYSTYRENE JTS	0 1000	L	W	M	L	L	H	Y	Y	023
	T FG LINE JT	0 1000	L	O	L	L	L	L	Y	Y	028
003 ROOM 30 ART	S TROWEL ON CEIL	900 0	L	O	L	L	L	L	Y	Y	017
	M 9 X 9 FT	900 0	L	O	L	L	L	L	Y	Y	016
004 ART WORK ROOM	S TROWEL ON CEIL	250 0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	250 0	L	O	L	L	L	L	N	Y	016
	M LAB TABLE TOP	150 0	L	O	L	L	L	L	N	N	018
005 ART STORAGE	S TROWEL ON CEIL	120 0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	120 0	L	O	L	L	L	L	N	Y	016

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR		FRI-	ASBES			
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
006 ROOM 28	S TROWEL ON CEIL	900	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	900	0	L	O	L	L	L	L	N	Y	016
007 ROOM 26 AND WORK ROOM	S TROWEL ON CEIL	1050	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	1050	0	L	O	L	L	L	L	N	Y	016
008 DARK ROOM	M 9 X 9 FT	150	0	L	O	L	L	L	L	N	Y	016
	M LAB TABLE	50	0	L	O	L	L	L	L	N	N	018
009 ROOM 24	S TROWEL ON CEIL	1600	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	1600	0	L	O	L	L	L	L	N	Y	016
010 COUNSELING CENTER	S TROWEL ON CEIL	1500	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	1500	0	L	O	L	L	L	L	N	Y	016
	M 2 X 4 DCT	240	0	L	O	L	L	L	H	Y	N	020
011 STAFF ROOM	S TROWEL ON CEIL	400	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	400	0	L	O	L	L	L	L	N	Y	016
012 JANITOR STORAGE	NO SUSP ACBM	0	0							N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. H.A. (Y,N,A)	NO.
013 GIRL'S RR X-FROM COUNSEL	NO SUSP ACBM	0	0							N	N	000
014 STG NEXT TO WOMEN'S RR	NO SUSP ACBM	0	0							N	N	000
015 BOY'S REST ROOM	NO SUSP ACBM	0	0							N	N	000
016 BAND INSTRUMENT STG RM	M 9 X 9 FT T HEAT LINE	120	0	L	O	L	L	L	L	N	Y	016
		0	20	L	O	H	L	L	H	N	Y	021
017 BAND ROOM	S TROWEL ON CEIL	1400	0	L	O	L	L	L	H	N	Y	017
018 PRACTICE RM & OFFICES	S TROWEL ON CEIL	600	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	600	0	L	O	L	L	L	L	N	Y	016
019 BAND STORAGE ROOM	T HEAT LINES	0	25	L	O	M	L	L	H	N	Y	021
	T HEAT LINE JTS	0	3	L	O	M	L	L	H	N	Y	028
	M 9 X 9 FT	240	0	L	O	L	L	L	L	N	Y	016
020 HALLWAY NORTH-WEST	S TROWEL ON CEIL	3200	0	L	O	L	L	L	H	Y	Y	017
	M 9 X 9 FT	3000	0	L	O	L	L	L	L	N	Y	016

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
021												
JANITOR'S CLOSET	T HEAT LINE	0	20	L	O	M	L	L	H	N	Y	021
	T JTS TO HEAT LN	0	3	L	O	M	L	L	H	N	Y	028
022												
ROOM 27 WOOD SHOP	T CELLULOSE LN	0	8	L	O	L	L	L	H	N	Y	023
	T ROOF DRAIN JT	0	4	L	O	L	L	L	H	N	Y	027
	T HEAT LINE	0	35	L	O	L	L	L	H	N	Y	021
	T HEAT LINE JTS	0	15	L	O	L	L	L	H	N	Y	028
023												
PAINT ROOM	M DOOR SEAL	0	3	L	O	H	L	L	H	Y	Y	025
024												
SHOP OFFICE	NO SUSP ACBM	0	0							N	N	000
025												
WOOD SHOP STORAGE	T HEAT LINES	0	15	H	V	H	L	L	H	N	Y	021
	T JOINTS	0	5	H	V	H	L	L	H	Y	Y	029
026												
SHOP MECHANICAL STORAGE	M TRANSITE BOARD	300	0	H	V	H	L	L	L	Y	Y	019
	M FIRE BRICK	1	0	H	V	H	L	L	L	Y	N	022
	T HEAT LINE	0	25	M	V	H	L	L	H	N	N	021
	T HEAT JOINTS	0	25	M	V	H	L	L	H	N	Y	028
	T ROOF DRAIN (2)	0	14	L	O	L	L	L	H	N	Y	027

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
026 SHOP MECHANICAL STORAGE	T ROOF DRAIN JTS	0	8	L	O	L	L	L	H	N	Y	027
027 WEIGHT ROOM	NO SUSP ACBM	0	0							N	N	000
028 MAINTAINENCE OFFICE	NO SUSP ACBM	0	0							N	N	000
029 STG NEXT MAINTENANCE OFC	NO SUSP ACBM	0	0							N	N	000
030 MEN'S ROOM	NO SUSP ACBM	0	0							N	N	000
031 RECEIVING RM OFF BLRM	NO SUSP ACBM	0	0							N	N	000
032 ATHLETIC DIRECTOR'S OFC	NO SUSP ACBM	0	0							N	N	000
033 ELECTRICAL ROOM	NO SUSP ACBM	0	0							N	N	000
034 KITCHEN OFC STG AND RR	T LNS VENT HOOD	19	0	L	O	M	L	L	H	N	N	019
	T JOINTS	0	12	L	O	M	L	L	H	N	Y	029
035 CAFETERIA STORAGE	NO SUSP ACBM	0	0							N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WD AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A.
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	
036										
CAFETORIUM	S									
	TROWEL ON CEIL	3800	0	L	O	L	L	L	H	Y Y 017
	M									
	9 X 9 FT	3200	0	L	O	L	L	L	L	Y Y 016
037										
STAGE AND STORAGE	S									
	TROWEL ON CEIL	2500	0	L	O	L	L	L	H	N Y 017
	T									
	HEAT LN STAGE	0	30	H	V	H	L	L	H	Y Y 029
	T									
	JOINTS	0	8	L	O	L	L	L	H	Y Y 029
038										
CONCESSION STAND	S									
	TROWEL ON CEIL	75	0	L	O	L	L	L	H	N Y 017
	M									
	9 X 9 FT	75	0	L	O	L	L	L	L	N Y 016
039										
CONFERENCE ROOM & CLOSET	S									
	TROWEL ON CEIL	200	0	L	O	L	L	L	H	Y Y 017
040										
STG RMS WOMEN'S REST ROOMS	S									
	TROWEL ON CEIL	100	0	L	O	L	L	L	H	N Y 017
	M									
	9 X 9 FT	100	0	L	O	L	L	L	L	N Y 016
041										
MAIN OFFICE AND CLOSET	S									
	TROWEL ON CEIL	650	0	L	O	L	L	L	H	N Y 017
	M									
	9 X 9 FT	650	0	L	O	L	L	L	L	N Y 016
042										
SUPPLY ROOM FOR OFFICE	S									
	TROWEL ON CEIL	70	0	L	O	L	L	L	H	N Y 017
	M									
	9 X 9 FT	50	0	L	O	L	L	L	L	N Y 016

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A. NO.		
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)		CONT. (Y,N,A)	
043 MIDDLE OFFICE AND CLOSET S	TROWEL ON CEIL	225	0	L	O	L	L	L	H	N	Y	017
044 END OFFICE	S TROWEL ON CEIL	225	0	L	O	L	L	L	H	N	Y	017
045 LIBRARY AND PERIODICAL RMS	TROWEL ON CEIL	1500	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	1500	0	L	O	L	L	L	L	N	Y	016
046 COMPUTER LAB	S TROWEL ON CEIL	1300	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	1300	0	L	O	L	L	L	L	N	Y	016
047 SUPERINTENDENT'S OFFICE	S TROWEL ON CEIL	400	0	L	O	L	L	L	H	N	Y	017
048 RECEPTION AREA AND VAULT S	TROWEL ON CEIL	450	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	80	0	L	O	L	L	L	L	N	Y	016
049 JANITOR'S CLOSET COMP LAB	NO SUSP ACBM	0	0							N	N	000
050 LIBRARY HALLWAY	S TROWEL ON CEIL	1150	0	L	O	L	L	L	H	Y	Y	017
051 HALLWAY CAFETORIUM	S TROWEL ON CEIL	3100	0	L	O	L	L	L	H	Y	Y	017

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO AS

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR			FRI-	ASBES		H.A. NO.
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)		
052 SOUTH GYM HALLWAY	S TROWEL ON CEIL	1050	0	L	O	L	L	L	H	N	Y	017
053 FRONT ENTRANCE FOYER	S TROWEL ON CEIL	950	0	L	O	L	L	L	H	N	Y	017
054 WORD PROCESSING LAB	S DCT	270	0	L	V	M	L	L	H	Y	N	020
	M 9 X 9 FT	270	0	L	O	L	L	L	L	N	Y	016
055 BOY'S LOCKER ROOM	M 9 X 9 FT	150	0	L	O	L	L	L	L	N	Y	016
	T HEAT PIPES	0	40	L	M	H	L	L	H	N	Y	021
	T JOINTS	0	4	L	M	H	L	L	H	Y	Y	029
056 GYMNASIUM	T ROOF DRAIN CELL	0	80	L	O	H	L	L	M	Y	Y	027
	T ROOF DRAIN JTS	0	16	L	O	H	L	L	M	Y	Y	027
	T HEAT LINES	0	120	L	O	H	L	L	H	N	Y	021
	T HEAT LINE JTS	0	32	L	O	H	L	L	H	N	Y	028
057 GYM STORAGE	T HEAT LINE	0	10	L	O	L	L	L	H	N	Y	021
	T HEAT LINE JTS	0	8	L	O	L	L	L	H	N	Y	028
058 GIRL'S LOCKER ROOM	NO SUSP ACBM	0	0							N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE (L,M,H)	DAMAGE POTENT.		AIR (L,M,H)	FRI- (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
				CAUSE (L,M,H)	CONTACT (L,M,H)							
059												
LOCKER ROOM STG OF GYM	T HEAT LINE	0 20	L	O	L	L	L	L	H	N	Y	021
	T HEAT LINE JTS	0 15	L	O	L	L	L	L	H	N	Y	028
060												
COACHES OFFICE	M 9 X 9 FT	120	0	L	O	L	L	L	L	N	Y	016
061												
SOUTH EAST HALLWAY	S TROWEL ON CEIL	3200	0	L	O	L	L	L	H	Y	Y	017
	M 9 X 9 FT	3200	0	L	O	L	L	L	L	N	Y	016
062												
ROOM 1 AND 2 ATTACHED	S TROWEL ON CEIL	1350	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	1350	0	L	O	L	L	L	L	N	Y	016
063												
ROOM 3	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016
064												
ROOM 5	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016
065												
ROOM 7	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR			FRI-	ASBES		
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
066 ROOM 9	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016
067 ROOM 11	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	Y	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016
068 NEW ADDITION ROOM 13	S TROWEL ON CEIL	800	0	L	W	L	L	L	H	Y	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	Y	Y	016
069 ROOM 14	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016
070 OLDER SECTION ROOM 12	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016
071 ROOM 10	S TROWEL ON CEIL	800	0	L	O	L	L	L	L	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	L	N	Y	016
072 ROOM 8	S TROWEL ON CEIL	675	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	675	0	L	O	L	L	L	L	N	Y	016

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR			FRI-	ASBES		
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.	
073												
ROOM 6 TYPING ROOM	S TROWEL ON CEIL	800	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	800	0	L	O	L	L	L	H	N	Y	016
074												
ROOM 4 SCIENCE ROOM	S TROWEL ON CEIL	950	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	950	0	L	O	L	L	L	L	Y	Y	016
	M LAB TABLE TOPS	300	0	L	O	L	L	L	L	Y	N	018
	M TRANSITE HOOD	100	0	L	O	H	L	L	L	Y	Y	019
075												
2 ROOMS BETWEEN 2 AND 4	S TROWEL ON CEIL	100	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	250	0	L	O	L	L	L	L	N	Y	016
	T HEAT LINES	0	8	L	O	L	L	L	H	N	Y	021
	T HEAT LINE JTS	0	8	L	O	L	L	L	H	N	Y	028
	M LAB TABLE TOPS	50	0	L	O	H	L	L	L	N	N	018
076												
ROOM 2	S TROWEL ON CEIL	900	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	900	0	L	O	L	L	L	L	N	Y	016
	M LAB TABLE TOPS	250	0	L	O	H	L	L	L	N	N	018
077												
ROOM 2 STORAGE	S TROWEL ON CEIL	225	0	L	O	L	L	L	H	N	Y	017
	M 9 X 9 FT	225	0	L	O	L	L	L	L	N	Y	016

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD HIGH SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.		AIR	FRI-	ASBES	H.A. NO.		
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)		ABILITY (L,M,H)	SAMPLES (Y,N)
078 SMALL REST ROOM BY RM 2	NO SUSP ACBM	0	0						N	N	000
079 GIRL'S & BOY'S REST ROOM	NO SUSP ACBM	0	0						N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
001 BOILER ROOM	M BOILER GASKET	0	12	L	O	L	L	L	M	Y	Y	007
	M BOILER GASKET	0	6	L	O	L	L	L	M	Y	Y	007
002 MUSIC ROOM 204	NO SUSP ACBM	0	0							N	N	000
003 MUSIC RM OFC STG PRACTICES	2 X 4 DCT	420	0	L	O	L	L	L	M	N	N	005
	M 12 X 12 FT	80	0	L	O	L	L	L	L	N	Y	006
004 ROOM 206	S 2 X 4 DCT	200	0	L	V	H	L	L	M	N	N	005
005 ROOM 301 STORAGE	S 2 X 4 DCT	100	0	L	O	L	L	L	M	N	N	005
	M 12 X 12 FT	100	0	L	O	L	L	L	L	N	Y	006
006 CONFERENCE ROOM 304	S 2 X 4 DCT	100	0	L	O	L	L	L	M	N	N	005
007 SCIENCE LAB RM 305	M 12 X 12 FT	1200	0	L	O	L	L	L	L	N	Y	006
008 ROOM 306	NO SUSP ACBM	0	0							N	N	000
009 ROOM 307												

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
009 ROOM 307	NO SUSP ACBM	0	0							N	N	000
010 CONFERENCE ROOM 308-309	S 2 X 4 DCT	150	0	L	O	L	L	L	M	N	N	005
011 ROOM 310	NO SUSP ACBM	0	0							N	N	000
012 CONFERENCE ROOM OF 310	S 2 X 4 DCT	100	0	L	O	L	L	L	M	N	N	005
013 ROOM 311	NO SUSP ACBM	0	0							N	N	000
014 ROOM 312	NO SUSP ACBM	0	0							N	N	000
015 STORAGE ROOM 313	S 2 X 4 DCT M 12 X 12 FT	100 100	0 0	L L	O O	L L	L L	L L	M L	Y N	N Y	005 006
016 CONFERENCE ROOM 314	S 2 X 4 DCT	100	0	L	O	L	L	L	M	N	N	005
017 ROOM 315	NO SUSP ACBM	0	0							N	N	000
018 ROOM 319	NO SUSP ACBM	0	0							N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES		H.A. NO.	
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)		CONT. (Y,N,A)
019 ROOM 320	NO SUSP ACBM	0	0							N	N	000
020 ROOM 321 CONFERENCE ROOM S	2 X 4 DCT	100	0	L	O	L	L	L	M	N	N	005
021 STORAGE ROOM 322	S 2 X 4 DCT	80	0	L	O	L	L	L	M	N	N	005
	M 12 X 12 FT	80	0	L	O	L	L	L	L	N	Y	006
022 ROOM 323	NO SUSP ACBM	0	0							N	N	000
023 ROOM 324	NO SUSP ACBM	0	0							N	N	000
024 ROOM 325	NO SUSP ACBM	0	0							N	N	000
025 CONFERENCE ROOM 326	S 2 X 4 DCT	80	0	L	O	L	L	L	M	N	N	005
026 CONFERENCE ROOM 327	S 2 X 4 DCT	80	0	L	O	L	L	L	M	N	N	005
027 ROOM 328	NO SUSP ACBM	0	0							N	N	000
028 ROOM 329	NO SUSP ACBM	0	0							N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WD KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A. NO.		
			DAMAGE (L,M,H)	CAUSE (DWVD)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)		CONT. (Y,N,A)	
029 CONFERENCE ROOM 330	S 2 X 4 DCT	100	0	L	O	L	L	L	M	N	N	005
030 HOME EC ROOM 207	S 2 X 4 DCT	50	0	L	O	L	L	L	M	Y	N	005
	M 12 X 12 FT	100	0	L	O	L	L	L	L	N	Y	006
031 ART ROOM 208 AND STG RM	M 12 X 12 FT	900	0	L	O	L	L	L	L	N	Y	006
	M KILN	50	0	M	D	H	L	L	M	Y	N	009
032 RM 209 AND 3 STG CLOSETS	M 12 X 12 FT	900	0	L	O	L	L	L	L	Y	Y	006
033 GYMNASIUM	NO SUSP ACBM	0	0							N	N	000
034 BALCONY STG RM 105	M 12 X 12 FT	3200	0	L	O	L	L	L	L	Y	Y	006
035 BALCONY STG RMS	NO SUSP ACBM	0	0							N	N	000
036 MECHANICAL RM GYM & LRS	NO SUSP ACBM	0	0							N	N	000
037 BOY'S LOCKER ROOM	M 12 X 12 FT	550	0	L	O	L	L	L	L	N	Y	006

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A. NO.
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	
038										
TRAINING RM OFC RR ENT	S									
	2 X 4 DCT	200	0	L	O	L	L	L	M	N N 005
	M									
	12 X 12 FT	200	0	L	O	L	L	L	L	N Y 006
039										
BOY'S MUD RM OFF LR	M									
	12 X 12 FT	300	0	L	O	L	L	L	L	N Y 006
040										
LOCKER ROOM HALLWAY	S									
	2 X 4 DCT	1050	0	L	V	M	L	L	M	Y N 005
	M									
	12 X 12 FT	1050	0	L	O	L	L	L	L	N Y 006
041										
STORAGE RM 103	M									
	12 X 12 FT	50	0	L	O	L	L	L	L	N Y 006
042										
GIRL'S LOCKER ROOM 104	M									
	12 X 12 FT	550	0	L	O	L	L	L	L	N Y 006
043										
STG OFC TRAINING RM	S									
	2 X 4 DCT	200	0	L	O	L	L	L	M	N N 005
	M									
	12 X 12 FT	200	0	L	O	L	L	L	L	N Y 006
044										
STORAGE RM 107	M									
	12 X 12 FT	35	0	L	O	L	L	L	L	N Y 006
045										
BIG HALL (CORRIDOR)-ENTNCS										
	2 X 4 DCT	2100	0	L	O	M	L	L	M	Y N 005
	M									
	12 X 12 FT	2100	0	L	O	L	L	L	L	N Y 006

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.			AIR	FRI-	ASBES			
		SF	LF	DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. (Y,N,A)	H.A. NO.
046 BOY'S TOILET EAST SIDE	NO SUSP ACBM	0	0							N	N	000
047 JANITOR'S CLOSET RM 201	M 12 X 12 FT	25		0	L	O	L	L	L	L	N	Y 006
048 GIRL'S TOILET	NO SUSP ACBM	0	0							N	N	000
049 ROOM 202	M 12 X 12 FT	80		0	L	O	L	L	L	L	N	Y 006
050 KITCHEN TRAY RM TOILET	M 12 X 12 FT	700		0	L	O	L	L	L	L	N	Y 006
051 STORAGE OFF KITCHEN	M 12 X 12 FT	250		0	L	O	L	L	L	L	N	Y 006
052 CAFETORIUM	M 12 X 12 FT	3600		0	L	O	L	L	L	L	N	Y 006
	S 2 X 4 DCT	130		0	L	O	M	L	L	M	Y	N 005
053 STAGE	M 12 X 12 FT	1400		0	L	O	L	L	L	L	N	Y 006
054 S HLWY OFF CAFETORIUM	S 2 X 4 DCT	600		0	L	O	M	L	L	M	Y	N 005
055 N HLWY OFF CAFETORIUM	S 2 X 4 DCT	600		0	L	O	M	L	L	M	N	N 005

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES		H.A. NO.		
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)		CONT. (Y,N,A)	
056 S HLWY LKR AREA BY MUS RMS	2 X 4 DCT	800	0	L	O	M	L	L	M	Y	N	005
057 LOCKER AREA	NO SUSP ACBM	0	0							N	N	000
058 N HALLWAY OFF LOCKER AREAS	2 X 4 DCT	1100	0	L	O	M	L	L	M	N	N	005
059 OFFICE ROOM 303	S 2 X 4 DCT	350	0	L	O	M	L	L	M	N	N	005
060 FIRST AID	S 2 X 4 DCT	100	0	L	O	M	L	L	M	N	N	005
	M 12 X 12 FT	100	0	L	O	L	L	L	L	N	Y	006
061 CONFERENCE ROOM	S 2 X 4 DCT	240	0	L	O	M	L	L	M	N	N	005
062 PRINCIPAL	S 2 X 4 DCT	160	0	L	O	M	L	L	M	N	N	005
063 WORK OFFICE (COPY ROOM)	S 2 X 4 DCT	12	0	L	O	M	L	L	M	N	N	005
	M 12 X 12 FT	120	0	L	O	L	L	L	L	N	Y	006
064 GIRL'S TOILET OFF LR	NO SUSP ACBM	0	0							N	N	000

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT SF & LF	DAMAGE POTENT.			AIR	FRI-	ASBES				
			DAMAGE (L,M,H)	CAUSE (DWVO)	CONTACT (L,M,H)	VIBRAT. (L,M,H)	EROSION (L,M,H)	ABILITY (L,M,H)	SAMPLES (Y,N)	CONT. H.A. (Y,N,A) NO.		
065 JANITOR'S CLOSET 302	M 12 X 12 FT	30	0	L	O	L	L	L	L	N	Y	006
066 BOY'S TOILET OFF LR	NO SUSP ACBM	0	0							N	N	000
067 S HALL OFF MEDIA CENTER	S 2 X 4 DCT	800	0	L	O	M	L	L	M	Y	N	005
068 MEDIA CENTER W HALL	S 2 X 4 DCT	800	0	L	O	M	L	L	M	N	N	005
069 T RM 334 OFF MEDIA CENTERS	2 X 4 DCT M	300	0	L	O	M	L	L	M	Y	N	005
	12 X 12 FT	30	0	L	O	L	L	L	L	N	Y	006
070 COUNSELOR'S RM 331 OFC	S 2 X 4 DCT	300	0	L	O	M	L	L	M	N	N	005
071 N HALL OFF MEDIA CENTER	S 2 X 4 DCT	800	0	L	O	M	L	L	M	Y	N	005
072 MEDIA RM 317 (AV ROOM)	S 2 X 4 DCT M	160	0	L	O	M	L	L	M	N	N	005
	12 X 12 FT	160	0	L	O	L	L	L	L	Y	Y	006
073 MEDIA RM 318 (WORK ROOM)	S 2 X 4 DCT	160	0	L	O	M	L	L	M	N	N	005

DELISLE ASSOCIATES LTD.
 ASBESTOS INSPECTION
 PHYSICAL ASSESSMENT OF ACM BY FUNCTION SPACE
 0414 BLISSFIELD PUBLIC SCHOOLS
 REPORT DATE: 11/03/89

BLDG: BLISSFIELD MIDDLE SCHOOL

INSPECTOR: WO KB

INSPECTION DATE: 06/02/88

FUNCTION SPACE NUMBER/DESCRIBE	MATERIAL TYPE/DESCRIBE	AMOUNT		DAMAGE POTENT.		AIR		FRI-	ASBES		
		SF	LF	(L,M,H)	(DWVO)	(L,M,H)	(L,M,H)	(L,M,H)	(L,M,H)	(Y,N)	(Y,N,A) NO.
074 ROOF PENTHOUSE	M BLACK TAPE	0	10	L	O	L	L	L	L	Y	N 008